



December 1, 2020

Sharon Meeuwsen  
NW Regional Education Service District  
5825 NE Ray Circle  
Hillsboro, Oregon 97124

Via email: sharonm@nwresd.k12.or.us

Regarding: District-Wide Short-Term Radon Testing  
PBS Project 27170.000 Phase 0001

Dear Ms. Meeuwsen:

From November 2 to 20, 2020, PBS Engineering and Environmental Inc. (PBS) performed short-term radon testing at various sites throughout Northwest Regional Education Service District (NWRESD).

### **TESTED LOCATIONS**

The following sites were communicated to PBS by NWRESD staff as eligible for testing and were tested by PBS:

- Beaverton Early Education Center – 9560 SW Nimbus Avenue, Beaverton
- Cascade Pacific Academies – 14255 SW Brigadoon Court, Beaverton
- Clatsop Service Center – 3194 Marine Drive, Astoria
- Columbia Service Center – 800 Port Avenue, Saint Helens
- Columbia Early Intervention – 800 Port Avenue, Saint Helens
- Day Treatment Program - 8770 SW Scoffins Road, Tigard
- Hillsboro Early Education Center – 759 SE Washington Street, Hillsboro
- Levi Anderson Learning Center – 16535 SW Tualatin Valley Highway, Beaverton
- Tualatin Early Education Center – 19500 SW 90th Street, Tualatin
- Washington Service Center – 5825 NE Ray Circle, Hillsboro

In several of the buildings above, NWRESD staff reported to PBS that they only use portions of the building and that the remaining locations in the building are used by other institutions. These specific locations were communicated to PBS and only those areas were tested. A comprehensive evaluation of the building was only completed if NWRESD utilized the full facility.

PBS endeavored to use sample location names based on existing room numbers or common-sense descriptions, but in buildings where no room number or other designation was available, PBS assigned names or numbers to the rooms.

### **METHODOLOGY**

The Environmental Protection Agency (EPA) recommends, and the Oregon Health Authority (OHA) requires, that school buildings be tested for radon, and that any radon concentrations be maintained below 4.0 picocuries per liter (pCi/L) of air. PBS used Air Chek, Inc., brand single-use, short-term radon test kits to measure radon levels in frequently-occupied rooms that are in contact with the ground or above unoccupied basements or crawlspaces.

Testing was conducted during the COVID-19 pandemic and NWRESD facilities were broadly unoccupied by the usual number of students and staff. However, several staff members were present and working in all of the buildings. PBS recommended that NWRESD set facility heating, ventilation, and air conditioning (HVAC) settings to typical parameters to simulate a fully-occupied building and to do so in advance of the scheduled testing. NWRESD communicated to PBS that this was done and PBS did not independently verify HVAC conditions. Testing was conducted during the winter heating season.

## RESULTS

Laboratory results identified short-term radon tests above 4.0 pCi/L in only one building, the Columbia Service Center. Specifically, results were found to be above 4.0 pCi/L in the fabrication room, office 7, and office 9, which are all located in the southeast portion of the building. However, because the building is relatively small, utilizes a common HVAC system, and showed results above 2.0 pCi/L throughout, it is reasonable to presume that a radon condition exists throughout the building.

Short-term tests in all nine other buildings were below 2.0 pCi/L. See the attached laboratory analysis summary for more details. See the attached field sketch of the Columbia Service Center building for location names chosen by PBS.

## RECOMMENDATIONS

In addition to the EPA recommendation that radon concentrations not exceed 4.0 pCi/L, OHA recommends that the following steps be conducted based on the results of a room's initial short-term test:

- **If the result is less than 2.0 pCi/L**, school districts are required to test again every 10 years, per Oregon Revised Statute 332.166-167.
- **If the result is between 2.0 pCi/L and 4.0 pCi/L**, consider fixing (i.e., lowering) the radon in that room.
- **If the result is from 4.0 pCi/L to 8.0 pCi/L**, perform a follow-up measurement of that room using a long-term test. This test should be conducted over as much of a nine-month school year as possible, when the room is likely to be occupied. If that result is equal to or greater than 4.0 pCi/L, the radon in the room should be fixed (i.e., lowered).
- **If the initial short-term test result is equal to or greater than 8.0 pCi/L**, conduct a second short-term test and average its result with the initial short-term test result. If the average of the two is equal to or greater than 4.0 pCi/L, radon in the room should be fixed (i.e., lowered).

Based on these recommendations, PBS recommends conducting long-term testing in three locations at the Columbia Service Center building. Short-term radon testing should be conducted again throughout the buildings in 2030.

## LIMITATIONS OF SCOPE

This study was limited to the tests and locations as previously indicated. The site as a whole may have other environmental concerns that will not be characterized by this study. The findings and conclusions of this work are not scientific certainties, but probabilities based on professional judgment concerning the significance of the data gathered during the course of this investigation. PBS is not able to represent conditions on the site or adjoining sites beyond those detected or observed by PBS.

Please feel free to contact me at 503.515.7489 or [james.mastanduno@pbsusa.com](mailto:james.mastanduno@pbsusa.com) with any questions or comments.

Sincerely,

James Mastanduno  
Project Manager

Attachments: Radon Sample Summary  
Columbia Service Center Locations

JM:mo

Radon test result report for:

**BEAVERTON EARLY EDUCATION CENTER  
MAIN**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9407924	BLANK	2020-11-12 @ 8:00 am	2020-11-12 @ 8:00 am	???? IB	2020-11-13
9407925	BLANK	2020-11-12 @ 8:00 am	2020-11-12 @ 8:00 am	???? IB	2020-11-13
9376298	LOBBY	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376287	NORTH AREA	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376257	NORTH AREA	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376275	NORTH AREA DUP	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376262	ROOM 1	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376282	ROOM 10	2020-11-09 @ 9:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376256	ROOM 11	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9367571	ROOM 12	2020-11-09 @ 9:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376268	ROOM 13	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9367581	ROOM 14	2020-11-09 @ 9:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376283	ROOM 15	2020-11-09 @ 9:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376260	ROOM 15 DUP	2020-11-09 @ 9:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376267	ROOM 16	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376271	ROOM 16 DUP	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376280	ROOM 17	2020-11-09 @ 9:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376300	ROOM 18	2020-11-09 @ 9:00 am	2020-11-12 @ 8:00 am	0.7 ± 0.3	2020-11-13
9376258	ROOM 2	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376293	ROOM 20	2020-11-09 @ 9:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376266	ROOM 22	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376272	ROOM 23	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376261	ROOM 25	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376286	ROOM 3	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376295	ROOM 4	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376284	ROOM 6	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376297	ROOM 7	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376255	ROOM 8	2020-11-09 @ 8:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13
9376288	ROOM 9	2020-11-09 @ 9:00 am	2020-11-12 @ 8:00 am	< 0.3	2020-11-13

Radon test result report for:  
**CASCADE PACIFIC ACADEMIES**  
**MAIN**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9368177	103 CONFERENCE	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9376279	BLANK	2020-11-06 @ 10:00 am	2020-11-06 @ 10:00 am	???? IB	2020-11-09
9376296	BLANK	2020-11-06 @ 10:00 am	2020-11-06 @ 10:00 am	???? IB	2020-11-09
9376278	BLANK	2020-11-06 @ 10:00 am	2020-11-06 @ 10:00 am	???? IB	2020-11-09
9368134	CAFETERIA	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	0.7 ± 0.3	2020-11-09
9368131	CAFETERIA DUP	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9336999	LOBBY	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368133	ROOM 107	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368180	ROOM 108	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368182	ROOM 109	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368184	ROOM 111	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368185	ROOM 112	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368181	ROOM 113	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368153	ROOM 116	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368183	ROOM 117	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368186	ROOM 118	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368152	ROOM 119	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368151	ROOM 120	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	0.6 ± 0.3	2020-11-09
9368128	ROOM 121	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368150	ROOM 123	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368179	ROOM 124	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368178	ROOM 124 DUP	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	0.5 ± 0.3	2020-11-09
9368135	ROOM 130	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368132	ROOM 131	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368130	ROOM 132	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	0.6 ± 0.3	2020-11-09
9368136	ROOM 135	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368129	ROOM 140	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	0.6 ± 0.3	2020-11-09
9368154	ROOM 141	2020-11-03 @ 9:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368088	ROOM 200	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	0.6 ± 0.3	2020-11-09
9368085	ROOM 201	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	< 0.3	2020-11-09
9368086	ROOM 202	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	< 0.3	2020-11-09
9368087	ROOM 202 DUP	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	0.5 ± 0.3	2020-11-09
9368083	ROOM 203	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	< 0.3	2020-11-09
9368082	ROOM 206	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	< 0.3	2020-11-09
9368081	ROOM 207	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	0.8 ± 0.3	2020-11-09
9368084	ROOM 208	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	0.6 ± 0.3	2020-11-09
9368149	ROOM 209	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	0.8 ± 0.3	2020-11-09

Radon test result report for:  
**CASCADE PACIFIC ACADEMIES**  
**MAIN**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9368080	ROOM 210	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	0.5 ± 0.3	2020-11-09
9368148	ROOM 211	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	0.7 ± 0.3	2020-11-09
9368146	ROOM 212	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	0.5 ± 0.3	2020-11-09
9368147	ROOM 214	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	0.5 ± 0.3	2020-11-09
9368145	ROOM 216	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368142	ROOM 217	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	0.6 ± 0.3	2020-11-09
9368144	ROOM 217 DUP	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	0.7 ± 0.3	2020-11-09
9368143	ROOM 218	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	0.6 ± 0.3	2020-11-09
9368140	ROOM 219	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	0.6 ± 0.3	2020-11-09
9368138	ROOM 220	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368141	ROOM 221	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368137	ROOM 222	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368139	ROOM 223	2020-11-03 @ 10:00 am	2020-11-06 @ 9:00 am	< 0.3	2020-11-09
9368099	ROOM 300	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	1.1 ± 0.3	2020-11-09
9368098	ROOM 301	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	1.3 ± 0.3	2020-11-09
9368093	ROOM 302	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	1.3 ± 0.3	2020-11-09
9368094	ROOM 302 DUP	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	1.2 ± 0.3	2020-11-09
9368100	ROOM 303	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	1.0 ± 0.3	2020-11-09
9368092	ROOM 305	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	1.0 ± 0.3	2020-11-09
9368095	ROOM 305 DUP	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	1.2 ± 0.3	2020-11-09
9368096	ROOM 306	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	0.8 ± 0.3	2020-11-09
9368097	ROOM 307	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	1.1 ± 0.3	2020-11-09
9368091	ROOM 309	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	0.6 ± 0.3	2020-11-09
9368090	ROOM 310	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	< 0.3	2020-11-09
9368089	ROOM 311	2020-11-03 @ 10:00 am	2020-11-06 @ 10:00 am	0.6 ± 0.3	2020-11-09

Radon test result report for:  
**CLATSOP SERVICE CENTER**  
**MAIN**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9336989	ASTORIA ROOM	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9376290	BLANK	2020-11-05 @ 12:00 pm	2020-11-05 @ 12:00 pm	???? IB	2020-11-06
9376254	BLANK	2020-11-05 @ 12:00 pm	2020-11-05 @ 12:00 pm	???? IB	2020-11-06
9336960	CLATSOP ROOM	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336967	EAST WORKROOM	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336973	ECSE CLASSROOM	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336959	EVAL ROOM	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336939	KITCHEN	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336957	NORTH OPEN AREA	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336958	NORTH OPEN AREA	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336981	OFFICE 10	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336976	OFFICE 11	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336975	OFFICE 12	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336982	OFFICE 13	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336974	OFFICE 14	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336965	OFFICE 16	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336966	OFFICE 16 DUP	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336945	OFFICE 20	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336941	OFFICE 20 DUP	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336946	OFFICE 21	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336936	OFFICE 22	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336938	OFFICE 23	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336943	OFFICE 26	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336935	OFFICE 26 EAST	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336986	OFFICE 6	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336985	OFFICE 7	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336984	OFFICE 8	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336983	OFFICE 9	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336940	P3 LENDING LIBRA	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336934	RECEPTION	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336968	RIVER ROOM	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336990	ROOM 18	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336954	ROOM 24	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336992	ROOM 25	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336995	ROOM 25 DUP	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336987	ROOM 5	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336988	ROOM 5 DUP	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06

---

November 6, 2020

**\*\* LABORATORY ANALYSIS REPORT \*\***

---

Radon test result report for:

**CLATSOP SERVICE CENTER  
MAIN**

---

<b>Kit #</b>	<b>Room Id</b>	<b>Started</b>	<b>Ended</b>	<b>pCi/L</b>	<b>Analyzed</b>
9336991	SE PLAY ROOM	2020-11-02 @ 10:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336937	STAFF ROOM	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336944	TODDLER	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06
9336942	WORK ROOM	2020-11-02 @ 9:00 am	2020-11-05 @ 9:00 am	< 0.3	2020-11-06

---

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498



Radon test result report for:

**COLUMBIA SERVICE CENTER  
MAIN**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9336908	BLANK	2020-11-05 @ 12:00 pm	2020-11-05 @ 12:00 pm	???? IB	2020-11-06
9368164	BOARDROOM	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	2.4 ± 0.3	2020-11-06
9368163	BOARDROOM DUP	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	2.1 ± 0.3	2020-11-06
9368167	BREAK ROOM	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	3.5 ± 0.3	2020-11-06
9368172	COPY ROOM	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	1.9 ± 0.3	2020-11-06
9368174	EVALUATION ROOM	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	2.4 ± 0.3	2020-11-06
9368165	FABRICATION ROOM	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	5.3 ± 0.3	2020-11-06
9368158	OFFICE 1	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	2.5 ± 0.3	2020-11-06
9368170	OFFICE 10	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	3.1 ± 0.3	2020-11-06
9368157	OFFICE 2	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	2.6 ± 0.3	2020-11-06
9368155	OFFICE 3	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	2.7 ± 0.3	2020-11-06
9368175	OFFICE 4	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	2.3 ± 0.3	2020-11-06
9368173	OFFICE 5	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	2.7 ± 0.3	2020-11-06
9368176	OFFICE 5 DUP	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	2.6 ± 0.3	2020-11-06
9368171	OFFICE 6	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	1.7 ± 0.3	2020-11-06
9368166	OFFICE 7	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	4.1 ± 0.3	2020-11-06
9368168	OFFICE 8	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	2.9 ± 0.3	2020-11-06
9368169	OFFICE 9	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	4.1 ± 0.3	2020-11-06
9368160	OFFICE WORK ROOM	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	2.1 ± 0.3	2020-11-06
9368161	RECEPTION	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	2.3 ± 0.3	2020-11-06
9368159	VISITORS ROOM 1	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	2.9 ± 0.3	2020-11-06
9368156	VISITORS ROOM 2	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	2.5 ± 0.3	2020-11-06

---

November 6, 2020

**\*\* LABORATORY ANALYSIS REPORT \*\***

---

Radon test result report for:

**COLUMBIA EARLY INTERVENTION  
MAIN**

---

<b>Kit #</b>	<b>Room Id</b>	<b>Started</b>	<b>Ended</b>	<b>pCi/L</b>	<b>Analyzed</b>
9376259	BLANK	2020-11-05 @ 12:00 pm	2020-11-05 @ 12:00 pm	???? IB	2020-11-06
9336994	EAST CLASSROOM	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	< 0.3	2020-11-06
9336996	MID CLASSROOM	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	< 0.3	2020-11-06
9336998	MID CLASSROOM DU	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	< 0.3	2020-11-06
9336997	OFFICE	2020-11-02 @ 12:00 pm	2020-11-05 @ 11:00 am	< 0.3	2020-11-06

---

Air Chek 1936 Butler Bridge Rd, Mills River, NC 28759-3892 Phone: (828) 684-0893 Fax: (828) 684-8498

Radon test result report for:

**DAY TREATMENT PROGRAM  
MAIN**

<b>Kit #</b>	<b>Room Id</b>	<b>Started</b>	<b>Ended</b>	<b>pCi/L</b>	<b>Analyzed</b>
9407796	BLANK	2020-11-20 @ 9:00 am	2020-11-20 @ 9:00 am	???? IB	2020-11-23
9407793	CAFETERIA	2020-11-17 @ 8:00 am	2020-11-20 @ 8:00 am	< 0.3	2020-11-23
9407767	GYM	2020-11-17 @ 8:00 am	2020-11-20 @ 8:00 am	0.5 ± 0.3	2020-11-23
9407783	GYM	2020-11-17 @ 8:00 am	2020-11-20 @ 8:00 am	0.6 ± 0.3	2020-11-23
9407774	NE CLASSROOM	2020-11-17 @ 8:00 am	2020-11-20 @ 8:00 am	< 0.3	2020-11-23
9407799	ROOM 34	2020-11-17 @ 8:00 am	2020-11-20 @ 8:00 am	< 0.3	2020-11-23
9407794	ROOM 35	2020-11-17 @ 8:00 am	2020-11-20 @ 8:00 am	< 0.3	2020-11-23
9407775	ROOM 36	2020-11-17 @ 8:00 am	2020-11-20 @ 8:00 am	< 0.3	2020-11-23
9407798	ROOM 37	2020-11-17 @ 8:00 am	2020-11-20 @ 8:00 am	< 0.3	2020-11-23
9407792	ROOM 37 DUP	2020-11-17 @ 8:00 am	2020-11-20 @ 8:00 am	< 0.3	2020-11-23
9407766	ROOM 41	2020-11-17 @ 8:00 am	2020-11-20 @ 8:00 am	3.2 ± 0.3	2020-11-23
9407800	ROOM 43	2020-11-17 @ 8:00 am	2020-11-20 @ 8:00 am	0.7 ± 0.3	2020-11-23

Radon test result report for:

**HILLSBORO EARLY EDUCATION CENTER  
MAIN**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9407982	BLANK	2020-11-12 @ 10:00 am	2020-11-12 @ 10:00 am	???? IB	2020-11-13
9407985	BLANK	2020-11-12 @ 10:00 am	2020-11-12 @ 10:00 am	???? IB	2020-11-13
9378286	FRONT DESK	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	< 0.3	2020-11-13
9407937	LIBRARY	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	< 0.3	2020-11-13
9376299	NORTH OFFICES	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	0.7 ± 0.3	2020-11-13
9376274	NORTH OFFICES	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	0.6 ± 0.3	2020-11-13
9376273	PRINCIPALS OFF	2020-11-09 @ 10:00 am	2020-11-12 @ 10:00 am	1.0 ± 0.3	2020-11-13
9407987	ROOM 10	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	< 0.3	2020-11-13
9407991	ROOM 11	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	< 0.3	2020-11-13
9407928	ROOM 14	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	0.6 ± 0.3	2020-11-13
9407993	ROOM 20	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	< 0.3	2020-11-13
9407905	ROOM 23	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	< 0.3	2020-11-13
9407989	ROOM 24	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	< 0.3	2020-11-13
9407990	ROOM 25	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	< 0.3	2020-11-13
9407988	ROOM 26	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	0.5 ± 0.3	2020-11-13
9378276	ROOM 34	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	0.6 ± 0.3	2020-11-13
9378284	ROOM 35	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	0.5 ± 0.3	2020-11-13
9378294	ROOM 36	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	< 0.3	2020-11-13
9407999	ROOM 37	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	< 0.3	2020-11-13
9407923	ROOM 4	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	< 0.3	2020-11-13
9378295	ROOM 43	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	< 0.3	2020-11-13
9407971	ROOM 44	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	< 0.3	2020-11-13
9407969	ROOM 46	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	0.5 ± 0.3	2020-11-13
9378296	ROOM 47A	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	0.5 ± 0.3	2020-11-13
9407907	ROOM 47B	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	< 0.3	2020-11-13
9407998	ROOM 48	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	< 0.3	2020-11-13
9407992	ROOM 48 DUP	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	0.5 ± 0.3	2020-11-13
9378285	ROOM 8	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	1.0 ± 0.3	2020-11-13
9378283	ROOM 8 DUP	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	1.1 ± 0.3	2020-11-13
9407938	ROOM 9	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	1.0 ± 0.3	2020-11-13
9378299	STAFF ROOM	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	0.5 ± 0.3	2020-11-13
9407906	WORK ROOM	2020-11-09 @ 11:00 am	2020-11-12 @ 10:00 am	0.7 ± 0.3	2020-11-13

Radon test result report for:

**LEVI ANDERSON LEARNING CENTER  
MAIN**

<b>Kit #</b>	<b>Room Id</b>	<b>Started</b>	<b>Ended</b>	<b>pCi/L</b>	<b>Analyzed</b>
9407994	BLANK	2020-11-12 @ 9:00 am	2020-11-12 @ 9:00 am	???? IB	2020-11-13
9376276	CONFERENCE	2020-11-09 @ 10:00 am	2020-11-12 @ 9:00 am	< 0.3	2020-11-13
9376265	MAIN OFFICE	2020-11-09 @ 10:00 am	2020-11-12 @ 9:00 am	< 0.3	2020-11-13
9376263	ROOM 1	2020-11-09 @ 10:00 am	2020-11-12 @ 9:00 am	< 0.3	2020-11-13
9376285	ROOM 2	2020-11-09 @ 10:00 am	2020-11-12 @ 9:00 am	< 0.3	2020-11-13
9376289	ROOM 3	2020-11-09 @ 10:00 am	2020-11-12 @ 9:00 am	< 0.3	2020-11-13
9376291	ROOM 4	2020-11-09 @ 10:00 am	2020-11-12 @ 9:00 am	0.9 ± 0.3	2020-11-13
9376294	ROOM 5	2020-11-09 @ 10:00 am	2020-11-12 @ 9:00 am	< 0.3	2020-11-13
9376292	ROOM 5 DUP	2020-11-09 @ 10:00 am	2020-11-12 @ 9:00 am	0.6 ± 0.3	2020-11-13
9376269	ROOM 8	2020-11-09 @ 9:00 am	2020-11-12 @ 9:00 am	0.8 ± 0.3	2020-11-13
9376264	WORK ROOM	2020-11-09 @ 10:00 am	2020-11-12 @ 9:00 am	0.5 ± 0.3	2020-11-13

Radon test result report for:**TUALATIN EARLY EDUCATION CENTER  
MAIN**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9376270	BLANK	2020-11-06 @ 8:00 am	2020-11-06 @ 8:00 am	???? IB	2020-11-09
9368191	KITCHEN	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	< 0.3	2020-11-09
9368190	KITCHEN DUP	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	0.8 ± 0.3	2020-11-09
9337000	MOTOR SKILLS	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	< 0.3	2020-11-09
9368194	PRINCIPAL OFFICE	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	< 0.3	2020-11-09
9368196	RECEPTION	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	< 0.3	2020-11-09
9368200	ROOM 1	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	0.5 ± 0.3	2020-11-09
9368199	ROOM 2	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	< 0.3	2020-11-09
9368197	ROOM 3	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	0.6 ± 0.3	2020-11-09
9368198	ROOM 4	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	< 0.3	2020-11-09
9368162	ROOM 4 DUP	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	< 0.3	2020-11-09
9368187	ROOM 5	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	0.5 ± 0.3	2020-11-09
9368195	SMALL CONF ROOM	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	< 0.3	2020-11-09
9368193	SOUTH CUBICLES	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	0.5 ± 0.3	2020-11-09
9368192	SOUTH CUBICLES	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	0.5 ± 0.3	2020-11-09
9368189	TRAINING ROOM	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	< 0.3	2020-11-09
9368188	WORK ROOM	2020-11-03 @ 8:00 am	2020-11-06 @ 8:00 am	< 0.3	2020-11-09

Radon test result report for:

**WASHINGTON SERVICE CENTER  
MAIN**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9367753	100 RECEPTION	2020-11-16 @ 10:00 am	2020-11-19 @ 8:00 am	< 0.3	2020-11-20
9367736	104 WORKSTATIONS	2020-11-16 @ 10:00 am	2020-11-19 @ 8:00 am	< 0.3	2020-11-20
9367765	108 WORKSTATIONS	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367752	112 WORKSTATIONS	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367767	200 WORKSTATIONS	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367773	200 WORKSTATIONS	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367769	205 WORKSTATIONS	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367770	205 WORKSTATIONS	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367779	303 WORKSTATIONS	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367708	317 LUNCH ROOM	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367709	400 WORKSTATIONS	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367728	408 WORKSTATIONS	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367778	418 WORKSTATIONS	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367717	421 LOBBY	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9407790	BLANK	2020-11-19 @ 8:00 am	2020-11-19 @ 9:00 am	???? NI	2020-11-20
9407788	BLANK	2020-11-19 @ 8:00 am	2020-11-19 @ 9:00 am	???? NI	2020-11-20
9407778	BLANK	2020-11-19 @ 8:00 am	2020-11-19 @ 9:00 am	???? NI	2020-11-20
9407789	BLANK	2020-11-19 @ 8:00 am	2020-11-19 @ 9:00 am	???? NI	2020-11-20
9407787	BLANK	2020-11-19 @ 8:00 am	2020-11-19 @ 9:00 am	???? NI	2020-11-20
9367751	FISCAL SVS LOBBY	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367757	METING RM BY 111	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9407978	OFF BY 220	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367721	OFF BY 418	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367746	RECEPTION	2020-11-16 @ 9:00 am	2020-11-19 @ 8:00 am	< 0.3	2020-11-20
9407976	RECEPTION DUP	2020-11-16 @ 11:00 am	2020-11-19 @ 8:00 am	< 0.3	2020-11-20
9367756	ROOM 100	2020-11-16 @ 10:00 am	2020-11-19 @ 8:00 am	< 0.3	2020-11-20
9367750	ROOM 101	2020-11-16 @ 10:00 am	2020-11-19 @ 8:00 am	< 0.3	2020-11-20
9367748	ROOM 102	2020-11-16 @ 10:00 am	2020-11-19 @ 8:00 am	< 0.3	2020-11-20
9367739	ROOM 104	2020-11-16 @ 10:00 am	2020-11-19 @ 8:00 am	< 0.3	2020-11-20
9367763	ROOM 105	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367760	ROOM 106	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367762	ROOM 107	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367758	ROOM 111	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367764	ROOM 111 DUP	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367735	ROOM 112	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367712	ROOM 117	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367761	ROOM 117 DUP	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20

Radon test result report for:

**WASHINGTON SERVICE CENTER  
MAIN**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9367707	ROOM 118	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367737	ROOM 121	2020-11-16 @ 10:00 am	2020-11-19 @ 8:00 am	< 0.3	2020-11-20
9367771	ROOM 200	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367766	ROOM 200 DUP	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367800	ROOM 201	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367797	ROOM 202	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367780	ROOM 203	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367781	ROOM 204	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367755	ROOM 205	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367754	ROOM 206	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367759	ROOM 207	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367798	ROOM 208	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367776	ROOM 209	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367777	ROOM 210	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367799	ROOM 211	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367796	ROOM 212	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9407962	ROOM 213	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9407975	ROOM 214	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9378277	ROOM 216	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9407926	ROOM 217	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367785	ROOM 222	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9407972	ROOM 222 DUP	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9407973	ROOM 224	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9378293	ROOM 225	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9378288	ROOM 226	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9407986	ROOM 227	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9407970	ROOM 228	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9378287	ROOM 228 DUP	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9378292	ROOM 230	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9407984	ROOM 232	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9407983	ROOM 232 DUP	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367725	ROOM 300	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367701	ROOM 300 DUP	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367718	ROOM 301	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	0.8 ± 0.3	2020-11-20
9367710	ROOM 302	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367772	ROOM 303	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367702	ROOM 309	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20



Radon test result report for:

**WASHINGTON SERVICE CENTER  
MAIN**

Kit #	Room Id	Started	Ended	pCi/L	Analyzed
9367734	ROOM 310	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367720	ROOM 311	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	0.5 ± 0.3	2020-11-20
9367716	ROOM 311 DUP	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367730	ROOM 313	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367715	ROOM 315	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367711	ROOM 316	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367747	ROOM 317	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367744	ROOM 401	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	0.5 ± 0.3	2020-11-20
9367743	ROOM 403	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367742	ROOM 404	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367738	ROOM 405	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367705	ROOM 406	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367729	ROOM 407	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367726	ROOM 408	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367727	ROOM 409	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367724	ROOM 410	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367775	ROOM 411	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367774	ROOM 412	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367714	ROOM 413	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367768	ROOM 418	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367704	ROOM 419	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367745	ROOM 421	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367731	ROOM 422	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367703	ROOM 427	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367722	ROOM 502	2020-11-16 @ 10:00 am	2020-11-19 @ 8:00 am	< 0.3	2020-11-20
9367741	ROOM 503	2020-11-16 @ 10:00 am	2020-11-19 @ 8:00 am	< 0.3	2020-11-20
9367733	ROOM 505	2020-11-16 @ 10:00 am	2020-11-19 @ 8:00 am	< 0.3	2020-11-20
9367740	ROOM 505 DUP	2020-11-16 @ 10:00 am	2020-11-19 @ 8:00 am	< 0.3	2020-11-20
9367732	ROOM 506	2020-11-16 @ 10:00 am	2020-11-19 @ 8:00 am	< 0.3	2020-11-20
9367749	ROOM 507	2020-11-16 @ 10:00 am	2020-11-19 @ 8:00 am	< 0.3	2020-11-20
9367713	SOUTH IT ROOM	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9367723	SOUTH IT ROOM	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	0.5 ± 0.3	2020-11-20
9367719	TECH WORK AREA	2020-11-16 @ 10:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20
9378291	WAITING BY 232	2020-11-16 @ 11:00 am	2020-11-19 @ 9:00 am	< 0.3	2020-11-20